



MINING CONTROLS INC.

Subsidiary of Elgin National Industries, Inc.

P. O. Box 1141
Beckley, West Virginia 25801
304-252-6243
304-252-9257 fax

12-4-2009 Revised 12-11-2009

To all Mining Controls Inc. Customers
Notification & Recall

Dear MCI Customers

This notice is to inform you of a problem with grommet packing gland assemblies Shipped after July 20, 2009 and before November 1, 2009. The problem is with the material thickness of each grommet. The approved thickness of the grommet is 0.250 +/- 0.020. MSHA is aware of this and we are working together to correct the problem.

Action to be taken by MCI customers:

Options:

1. Check all grommets in stock and return bad grommets to MCI for replacement ASAP.
2. Ship all gland assemblies in your stock to MCI for inspection. MCI will check, and replace defective grommets, and return to customer.
3. If a gland assembly is being installed with incorrect grommets, it will be very clear since the gland nut will not tighten before the nut bottoms out against the housing. If this accurse when packing a gland or is found on a machine in service please check the grommets in use and contact MCI for replacement grommets.

It is my hope we can take care of this problem as soon as possible.

If you have any questions please call Larry Rowley @ 304-252-6243 ext 117

Sincerely,

Larry W. Rowley
Manager of Lighting & Camera Products
Mining Controls Inc.
304-252-6243 ext 147