

Mining Controls Inc. Grommet Recall

Grommet Packing Glands installed on underground equipment.

Question: Does this gland assembly have grommets that are too thin?

To inspect the gland assembly, use the following procedure :

1. Remove the locking device i.e. (lock screw or seal wire.)
2. With your hand, tighten the gland nut.
3. Check the gap between the housing and the side of the nut closest to the housing. If the gap is less than 1/8" replace the grommets and bushing.
(CONTACT MINING CONTROLS FOR REPLACEMENT GROMMET KITS)
4. If the gap is greater than 1/8", the gland assembly is good.
5. Replace the locking device.

Note : the movement of the gland hose tube has no bearing on whether the gland is properly packed.

If you have any questions please contact:

Lynn M. Huggins, Mining Engineer, QA & MTD MSHA 304-547-2073

higgins.lynn@dol.gov

Larry W Rowley, Manager of Lighting & Camera Products, Mining Controls Inc. 304-252-6243 ext 147

larry.rowley@elginindustries.com